

Ms Nompumelelo Simelane Nkangala District P O Box 437 MIDDLEBERG

Date 28 July 2025

Enquiries S Chokoe

1050
By email Simelanenl@nkangaladm gov za

Tel +27 13 647 6970

Dear Ms Nompumelelo Simelane

Ref Kendal Power Station AEL (17/4/AEL/MP312/11/15)

# SUBMISSION OF KENDAL POWER STATION'S EMISSIONS REPORT FOR THE MONTH OF JUNE 2025

This is a monthly report required in terms of Section 7.4 in the Kendal Power Station's Atmospheric Emission License. The emissions are for Eskom Kendal Power Station.

Compiled by

Tsakanı Holeni

**ENVIRONMENTAL SENIOR ADVISOR- KENDAL POWER STATION** Date:

Supported by

Solly Chokoe

ENVIRONMENTAL MANAGER- KENDAL POWER STATION

Date: 28 (で) /2025

G20 SOUTH AFRICA 2025

In partnership with

## KENDAL POWER STATION'S EMISSIONS REPORT FOR THE MONTH OF JUNE 2025

Verified by

Jacob Zwane

BOILER ENGINEERING: SENIOR SYSTEM ENGINEER- KENDAL POWER STATION Date:

Validated by

Tendanı Rasıvhetshele

**BOILER ENGINEERING MANAGER-KENDAL POWER STATION** 

Date:

Supported by

Phindile Takane

**ENGINEERING MANAGER-KENDAL POWER STATION** 

Date: 4-08-2025

Approved by


Tshepiso Temo

GENERAL MANAGER-KENDAL POWER STATION

Date: 0025 08 (X)

JUNE 2025

KENDAL POWER STATION MONTHLY EMISSIONS REPORT Atmospheric Emission License 17/4/AELMP312/11/15



# 1 RAW MATERIALS AND PRODUCTS

Raw Materials	Raw Material Type	Units	Maximum Permitted Consumption Rate	Consumption Rate Jun-2025
and	Coal	Tons	2 260 000	507 390
Products	Fuel Oil	Tons	5 000	9887.670
Day divellan	Product / By-Product Name	Units	Maximum Production Capacity Permitted	Indicative Production Rate Jun-2025
Production		Units		
Production Rates	Name	Units	Capacity Permitted	Rate Jun-2025

Note: Maximum energy rate is as per the maximum capacity stated in the AEL: [4 118 MW] x 24 hrs x days in Month/1000 to convert to GWh

### 2 ENERGY SOURCE CHARACTERISTICS

Coal Characteristic	Units	Stipulated Range	Monthly Average Content
CV Content	MJ/kg	16-24 (MJ/kg)	18.870
Sulphur Content	%	<1 (%)	0.860
Ash Content	%	40 (%)	31.610

### 3 EMISSION LIMITS (mg/Nm³)

Associated Unit/Stack	PM	SO <sub>2</sub>	NOx	
Unit 1	100	3500	1100	
Unit 2	100	3500	1100	
Unit 3	100	3500	1100	
Unit 4	100	3500	1100	
Unit 5	100	3500	1100	
Unit 6	100	3500	1100	

### 4 ABATEMENT TECHNOLOGY (%)

Associated Unit/Stack	Technology Type	Efficiency Jun-2025	Technology Type	SO <sub>3</sub> Utlization Jun-2025
Unit 1	ESP + SO,	98.923%	so,	60.0%
Unit 2	ESP + SO,	91.233%	SO,	13.3%
Unit 3	ESP + SO,	99.159%	SO,	96.7%
Unit 4	ESP + SO,	99.553%	SO,	20.0%
Unit 5	ESP + SO,	98.306%	SO,	23.3%
Unit 6	ESP + SO,	96.315%	SO,	56.7%

Note: ESP plant does not have bypass mode operation, hence plant 100% Utilised.

there is no Sulphur value for SO3 utilization due to switch failure on the server, however DCS signals used for its tripping alarms were used to get its utilization values. Sulphur (low will be available once we have commissioned the new PI system.

### 5 MONITOR RELIABILITY (%)

Associated Unit/Stack	PM	SO,	NO	O <sub>1</sub>
Unit 1	70.9	100.0	88.0	99.8
Unit 2	16.1	100.0	100.0	100.0
Unit 3	92.7	100.0	98.9	100.0
Unit 4	100.0	100.0	86.6	90.9
Unit 5	100.0	100.0	100.0	100.0
Unit 6	28.3	100.0	100.0	100.0

Note: NOx emissions is measured as NO in PPM. Final NOx value is expressed as total NO 2

### 6 EMISSION PERFORMANCE

Table 6.1: Monthly tonnages for the month of June 2025

Associated Unit/Stack	PM (tons)	SO <sub>2</sub> (tons)	NO <sub>x</sub> (tons)
Unit 1	307.9	2 055	620
Unit 2	724.1	485	173
Unit 3	313.0	2 230	501
Unit 4	36.0	661	152
Unit 5	274.2	997	472
Unit 6	1 105.1	1 941	851
SUM	2 760.37	8 368	2 769

Table 6.2: Operating days in compliance to PM AEL Limit - June 2025

Associated Unit/Stack	Normal	Grace	Section 30	Contraven tion	Total Exceedance	Average PM (mg/Nm <sup>2</sup> )
Unit 1	1	4	0	19	23	396.7
Unit 2	0	1	0	6	7	2 698.1
Unit 3	14	4	0	11	15	259.6
Unit 4	6	2	0	0	2	131.8
Unit 5	0	2	0	9	11	437.7
Unit 6	0	2	0	19	21	1 817.0
SUM	21	15	0	64	79	

Table 6.3: Operating days in compliance to SO<sub>2</sub> AEL Limit - June 2025

Associated Unit/Stack	Normal	Grace	Section 30	Contraven tion	Total Exceedance	Average SO <sub>2</sub> (mg/Nm <sup>1</sup> )
Unit 1	26	0	0	0	0	1 985,6
Unit 2	10	0	0	0	0	1 465.0
Unit 3	30	0	0	0	0	1 665.2
Unit 4	11	0	0	0	0	1 975.6
Unit 5	12	0	0	0	0	1 535.7
Unit 6	24	0	0	0	0	1 701.2
SUM		0	0	0	0	


Table 6.4: Operating days in compliance to NOx AEL Limit - June 2025

Associated Unit/Stack	Normal	Grace	Section 30	Contraven tion	Total Exceedance	Average NOx (mg/Nm²)
Unit 1	26	0	0	0	0	564.4
Unit 2	10	0	0	0	0	493.7
Unit 3	30	0	0	0	0	368.0
Unit 4	11	0	0	0	0	444.8
Unit 5	12	0	0	0	0	687.0
Unit 6	24	0	0	0	0	699.2
SUM	113	0	0	0	0	


Note: NOx emissions is measured as NO in PPM. Final NOx value is expressed as total NO 2

Table 6.5: Legend Description


Condition	Colour	Description	
Normal	GREEN	Emissions below Emission Limit Value (ELV)	
Grace	BLUE	Emissions above the ELV during grace period	
Section 30	ORANGE	Emissions above ELV during a NEMA S30 incident	
Contraventio	RED	Emissions above ELV but outside grace or S30 incident conditions	




High emissions can be attributed to the DUst Handling Plant that was standing, poor precip performance and dut to the F22/34 HV that was Faulty and tripping on low coolant level, it required a new radiator.




High emissions can be attributed to Field 13, 43 & 44 Com bus Fault, Field 17826 was O/C due to electrical issue. Œ rapper 13,4,5 Left Hand & 1-6 Right Hand tripping on overload.







High PM emissions can be attributed to the SO3 plant that was off due to Fire.





Nigh PM emissions can be attributed to the Dust Handling Plant that was standing.





High PM embsions can be attributed to the ash backlogs due to Dust Handling Plant running with PCP11-24 knije gates 1-3 that were closed.
































7 COMPLAINTS

There v. or. no complaints for this months.

Source Code / Inc. or.

	Nanye	Source Code ! R	
		Source Code / Root Course Analysis	
	emissions associated	Calculation of Impacts 1	
	where applicable	Dispersion modeling of pollutants	
	prevent reoccurrence	Peasures implemented to	

### Abatement Technology Table 4

In order to achieve the required operational dust removal efficiency based on measured values, several assumptions such as

E Coal ash content (%) and burnt rate mass

® Fly Coarse ash ratio of 80 20 80% of fly ash mass obtained from burnt coal goes to ESP 

☑ Measurement of dust emission by Dust Monitor over a period of time (monthly)

Operational Dust Removal Efficiency

 $n = (1 - (Output/Input)) \times 100$ 

 $\eta = 1$  {DustEmission1 romAQR ReportDustMonitor(tons) X 100 (CoalBurnt(tons)+%AshContent+80%)

### Monitor Reliability-Table 5

In terms of the minimum emissions standard, the requirement is that a monitor should be 80% reliable on a monthly average The monitor reliability refers to data reliability because the assumed value of 99 325% reliability is compared to the dust concentration signal If the dust concentration signal is above 99 325% opacity, the data information is no longer reliable because the monitor reading is out of its maximum reading range. The data reliability looks at how many times did the dust concentration signal go above 98% over a period of time e g 24hours

The formula is as follows
= (1 – (count hours above 99 325%/24hours) )x 100

- Emissions Performance

  Average velocity values from the latest correlation report were used on the gaseous emissions on Units due to defective CEMS monitors and velocity correction factors were set M=1 and C=0

  Unit 1,2,3 and 6 maxed out meaning the emissions were higher than vihal the monitor was correlated for in which case we use surrogate

- values This is attributed to abnormal plant conditions

  Please note that the reported figures in toninage calculation are the figures after the station used the maxing out quantification exercise which is the use of "surrogate values" on days when the monitor maxed out

  Flow was not working for the whole month because of sensors that are faulty and the sensors have to be replaced on all the units. The
- Flow was not working for the whole month because of sensors that are faulty and the sensors have to be replaced on all the units. The process for procuring new sensors is in progress.

  Correlation curves for units 1.4 and 5 were changed to suite changes of the data signals from "AAA" to "HME" data values because of the damaged cables for "AAA" signal giving values that were not reliable.

  Surrogation values were recalculated after updating raw data based on curves update.

  The OAL 2 average values for gaseous were used as raw data in cases where the monitor had an error were used as surogation values.

  The O2 sensors are faulty as they all need to be replaced. Unit 5 and 4 O2 sensors were replaced in July 2025 and the process of replacing the other sensors is in progress.

  The PM monitions were not 100% reliable due ash backlogs dust flooded the dust motors.

Unit 1
 Findings The high emissions can be attributed the DUst Handling Plant that was standing, poor precip performance and dut to the F22/34 HV that was Faulty and tripping on low coolant level, it required a new radiator

Resolution Plant repaired

- Findings Field 13, 43 & 44 Com bus Fault, Field 17&26 was O/C due to electrical issue CE rapper 1.3.4.5 Left Hand & 1 6 Right Hand
- tripping on overload

  Resolution Plant repaired

- Findings The high PM emissions can be attributed to the CE rapper 1,2,3, that kept on tripping on overload, Ash backlogs, Field 14,21,22 was tripping on low voltage due to ash backlogs and Precip chain 14 was standing Resolution Plant repaired

- Unit 4
  Findings The high PM emissions can be attributed to to the SO3 plant that was off due to Fire
- Resolution Plant repaired

- Findings High PM emissions can be attributed to the Dust Handling Plant that was standing
   Resolution Plant repaired

- Findings High PM emissions can be attributed to the ash backlogs due to Dust Handling Plant running with PCP11 24 knife gates 1 3 that were closed
- Resolution Plant repaired