




**CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST**

Template Identifier	240-43821888	3
Document Identifier	WFM/LD - 4.5.5/003	0
Authorisation Date	22-Nov-12	
Review Date	01-Nov-15	

NO	ENVIRONMENTAL ASPECTS	CONFORMANCE/ NON CONFORMANCE/COMPLIANCE	CORRECTIVE ACTION	EVIDENCE OF CHANGE	% RATING
<b>Environmental Policy</b>					
	<b>Environmental Management Plan (EMP) and Environmental Authorisation (EA) Training/Awareness</b>				
Has EA_EMP been communicated to an agent, sub-contractor, employee or any person rendering a service to the holder of the authorisation? This includes the Eskom SHEQ Policy and must be displayed.					
		Y	1. 25/12/2015 L13/2015 9/12/2015		1
<b>Planning - Environmental Aspects</b>					
<b>Working Areas</b>					
	Have construction activities remained within the designated working areas?	Y			1
	Inform the contractor about the no go areas/work restrictions i.e. sensitive vegetation/species and watercourses etc.				
	Is the housekeeping done neatly i.e. stockpiling of materials & equipment's etc.	Y			1
	Are vehicles parked in their demarcated parking areas?	Y			1
	Are working areas well defined with a	Y. Temporary fence.			1

**CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST**

		Template Identifier	240-43821888	3
		Document Identifier	WFNLD - 4.5.5003	0
		Authorisation Date	22-Nov-12	
		Review Date	01-Nov-15	
fence or danger tape, in case of powerline, the servitude width 18m for 11 – 22kV and 45m for 132kV				
<b>Property Access and Camp Establishment</b>				
Was permission obtained from the property owners before construction commence?				
Do the property owners have unrestricted access to their property?		Y.		—
Are all access roads and camp establishment created with the assistance of ECO /Botanist /Freshwater Specialist or Site Engineer? If applicable		N/A.		N/A.
Were entrance gates, walls, paths, roads and fence rehabilitated satisfactorily as per EA-EMP conditions i.e. landowners		To be assessed closer to end of construction.		—
<b>Vegetation Management</b>				
Are applicable permits available for indigenous vegetation clearance, cutting, disturbing, damaging or trimming of protected/endangered trees and monumental trees as per		N/A.		N/A.



**CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST**

Template Identifier	240-43921898	3
Document Identifier	WFWMLD - 4.5.5/003	0
Authorisation Date	22-Nov-12	
Review Date	01-Nov-15	

applicable SAHRA and City Bylaws acts?		
Is the servitude or working area cleared of alien vegetation as per 32-247 Standard for Bush Clearance and maintenance within overhead Powerline servitude procedure i.e. firebreak	Yes.	1
Have all bush clearing and herbicide methods been undertaken under the supervision of a registered Pest Control Officer (PCO) i.e. produce valid letter from DAFF	No herbicide usage	1
Clearance of vegetation in Critical Biodiversity Areas (CBA) must be done with an approved method statement by the ECO and or specialist recommendation as per EA i.e. site, area, height and timing	N/A.	N/A.
Spillages		
Is there a stock of adequate oil spill remediation kit i.e. oil spill kit	Absorbent pools bags, sponges, broom, Absorbent sponges	1
14.	Awaiting stock	1

a peat zorb.

<b>ESKOM</b>		<b>CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST</b>	
		Template Identifier      240-43921888      3 Document Identifier      WFM/LD - 0 Authorisation Date      22-Nov-12 Review Date      01-Nov-15	
15. Have any spill/leak occurred on site i.e. oil, chemical, diesel, paint, sewer and waste water. Are the spills/leaks visible from construction site		N.	
16. Have the spills been managed according to Western Cape Operating Unit Oil Spill Management Instruction reference no. 240-79588150.		N/A.	
<b>Natural Heritage Resources</b>			
17. Were there any tribal graves, archaeological and paleontological sites identified before or during the construction activities?		N.	
18. If yes, was construction stopped and the ECO contacted immediately?		N/A	
19. Was the Heritage Resource Agency or a Heritage Specialist contacted immediately?		N/A	
<b>Portable Toilet/Sanitation</b>			
20. Are there sufficient portable toilets i.e. 1:8 - 10 people and within walking distance		Y. Three.	
21. Portable toilets to be serviced weekly i.e. clean, smell good, toilet roll &		Y. 5/3/2015 & 26/12/2015.	



**CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST**

Template Identifier	240-43921888	3
Document Identifier	WFMLD - 4.5.5003	0
Authorisation Date	22-Nov-12	
Review Date	01-Nov-15	

functional at all times. Services receipts available		
Sanitation and ablution facilities should not result in an impact on the environment? Sewage spillage etc.	N.	1
<b>Integrated Waste Management</b>		
Is there an integrated waste management system in place i.e. intervals for waste disposal, bins labelled accordingly, proper waste storage and tightly contained, waste separation and recycling etc.	4. Labelled bins N.CS. Periodically when full.	1
Are there sufficient waste bins on site?	1.	1
Was litter noted during site inspection?	N.	1
Waste Manifest, Safe disposal certificate from the landfill site and Letter of agreement from the Municipality to comply with Waste General Notice (GN) No. 435 of 2011, Annexure 1 & 2. All other provisions of NEM-WA to be complied with if	4. Smartland toilet slips on site. Removed general waste on 27/12/2015 # 32039 & 6(3)205 # 32038.	1

 <b>Eskom</b>		<b>CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST</b>																																													
		<b>Template Identifier</b>	240-43921898 3																																												
		<b>Document Identifier</b>	WFN/LD - 0 4.5.5003																																												
		<b>Authorisation Date</b>	22-Nov-12																																												
		<b>Review Date</b>	01-Nov-15																																												
<table border="1"> <tr> <td colspan="2">applicable.</td> <td colspan="2"></td> </tr> <tr> <td colspan="2">Are the hazardous and non-hazardous products (paints, paste, chemicals etc.) labelled and have Material Safety Data Sheet (MSDS)?</td> <td colspan="2"></td> </tr> <tr> <td colspan="4"> <b>Additional Environmental Aspects</b> </td> </tr> <tr> <td colspan="4"> <p>Are there trained fire fighter and adequate fire-fighting equipment in appropriate places i.e. valid fire extinguisher</p> <p>Are there effective dust control (if necessary) measures in place.</p> <p>Are there noise control (if necessary) measures in place.</p> <p>Are there any erosion control (if necessary) measures in place?</p> <p>Are there top soil management in place i.e. separation of top soil vs. sub-soil, backfilling and levelling (if necessary)</p> <p>Is there any impact on the water resource - wetland, stormwater drain, river, stream, lake, dam and riparian</p> </td> </tr> <tr> <td colspan="2">27.</td> <td colspan="2">Yes</td> </tr> <tr> <td colspan="2">28.</td> <td colspan="2">Yes</td> </tr> <tr> <td colspan="2">29.</td> <td colspan="2">Yes</td> </tr> <tr> <td colspan="2">30.</td> <td colspan="2">No complaints.</td> </tr> <tr> <td colspan="2">31.</td> <td colspan="2">No issues</td> </tr> <tr> <td colspan="2">32.</td> <td colspan="2">Yes</td> </tr> <tr> <td colspan="2">33.</td> <td colspan="2">No</td> </tr> </table>				applicable.				Are the hazardous and non-hazardous products (paints, paste, chemicals etc.) labelled and have Material Safety Data Sheet (MSDS)?				<b>Additional Environmental Aspects</b>				<p>Are there trained fire fighter and adequate fire-fighting equipment in appropriate places i.e. valid fire extinguisher</p> <p>Are there effective dust control (if necessary) measures in place.</p> <p>Are there noise control (if necessary) measures in place.</p> <p>Are there any erosion control (if necessary) measures in place?</p> <p>Are there top soil management in place i.e. separation of top soil vs. sub-soil, backfilling and levelling (if necessary)</p> <p>Is there any impact on the water resource - wetland, stormwater drain, river, stream, lake, dam and riparian</p>				27.		Yes		28.		Yes		29.		Yes		30.		No complaints.		31.		No issues		32.		Yes		33.		No	
applicable.																																															
Are the hazardous and non-hazardous products (paints, paste, chemicals etc.) labelled and have Material Safety Data Sheet (MSDS)?																																															
<b>Additional Environmental Aspects</b>																																															
<p>Are there trained fire fighter and adequate fire-fighting equipment in appropriate places i.e. valid fire extinguisher</p> <p>Are there effective dust control (if necessary) measures in place.</p> <p>Are there noise control (if necessary) measures in place.</p> <p>Are there any erosion control (if necessary) measures in place?</p> <p>Are there top soil management in place i.e. separation of top soil vs. sub-soil, backfilling and levelling (if necessary)</p> <p>Is there any impact on the water resource - wetland, stormwater drain, river, stream, lake, dam and riparian</p>																																															
27.		Yes																																													
28.		Yes																																													
29.		Yes																																													
30.		No complaints.																																													
31.		No issues																																													
32.		Yes																																													
33.		No																																													



**CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST**

Template Identifier	240-43921688	3
Document Identifier	WFMILD - 4.5.5003	0
Authorisation Date	22-Nov-12	
Review Date	01-Nov-15	

vegetation?				
<b>Implementation and Operation - Resources, Roles, Responsibility and Authority</b>				
34.	Have environmental Roles and Responsibilities been assigned to relevant personnel? One (1) person to be appointed per team?	4. Hasie fo yeweli s		1
<b>Communication</b>				
35.	Has the Environmental Emergency Preparedness and Response (EEP/R) procedure (WPC020) being communicated to everyone on site?	4. EMP training		1
36.	Have the non-conformance report (NCR), Incidents and any other deviations being communicated to the project team?	Yes via Shore long per e-mail		1
37.	Has the contractor conducted weekly environmental awareness/toolbox sessions? Keep a signed attendance register.	4. On file.		1
38.	Have the relevant aspects of the Eskom procedures and instruction been communicated?	4. EMP training		1
<b>Documentation - Control of Documents</b>				
39.	Are there Eskom Procedures on file	4		1

 <b>CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST</b>		Template Identifier 240-43921698 Document Identifier WFM/LD - 0 Authorisation Date 22-Nov-12 Review Date 01-Nov-15
such as Waste Standards, Bush Clearing procedure and Oil Spill Instruction etc?		
<b>Environmental Emergency Preparedness and Response procedure (EPR)</b>		
Are the emergency numbers available and up-to-date to all construction personnel?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Is there an Environmental Emergency preparedness Procedure to deal with environment-related incidents (e.g. fires, oil spillages, snakes bites, bee stings etc.)? Eskom EPR procedure to be available and displayed on site.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<b>Checking - Non Conformity and Corrective Action Plan</b>		
Has there been any deviation from the requirements of EA-EMP, Permit, License, RoD and any other conditions or agreement?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
If any deviations, have they been reported to Environmental Works/Project Coordinator/Site Manager within 24 Hours e.g. oil & diesel spillages etc.	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Have the action plans been developed	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>



## CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST

Template Identifier	240-43021898	3
Document Identifier	WFM/LD - 455/003	0
Authorisation Date	22-Nov-12	
Review Date	01-Nov-15	

and incidents addressed adequately? Shall not exceed more than 24 Hours depending on the incident or action?		
Have all the Non Conformances Reports been addressed and closed e.g. complaints, incidents, pollution etc? If applicable	NIP	NIP
Control of Records		
Does the site have Environmental File with EA_EMP and Training records, Incidents Flash Reports, Permits, Licences, RoD, Waste Manifest, Letter of consent, NCR, Inventory of Incidents, Complaints Register, Action Plans and Audit Reports? To be produced when required at all times.	Y	1
Internal Audits		
Has the contractor performed a self-audit and addressed all deviations? Atleast one or more in two weeks?	Y . 6(3)2015 21/2/2015	1

	CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST		
	Template Identifier	240-43921698	3
	Document Identifier	WFWILD - 4.5.5003	0
	Authorisation Date	22-Nov-12	
	Review Date	01-Nov-15	

PROJECT DETAILS			
Name of the Project : Powerline or Substation	Ugellei SS	Name of the Auditor	M. Hechikse
Name of the Construction Representative	H. C. Collissen & Spaelberg	Date	10/03/2015
Signature	J.	Signature	

COMPLIANCE STATUS			
Number of Compliance	47		
Number of Non-Conformance	0		
Compliance Rating:	Compliant	X	
	Risk of non-compliant		
	Non-Compliant		
Percentage Compliance Scores	100%		

- \* Building control building.
- \* Steel fixing framework.