

Generation

Nkangala District Municipality

P O Box 437 Middleburg

1050

Attention:

Mr V Mahlangu

AND

Directorate: Air Quality Management

Services

The Chief Director:

Mr S S Maluleka

Department of Environmental Services

Private Bag X447

PRETORIA

0001

Tel: (012) 310 3263

Fax: (012) 320 0488

Date: 2022/12/20

Enquiries: Duvha Environmental Management

2 +27 13 690 0445

愚 +27 66 212 2105

Enquiries: Ms Simthandile Nhlapo

2 +27 13 690 0445

昌 +27 66 212 2105

Total number of pages: 14

Total number of annexes:1

DUVHA POWER STATION

Atmospheric Emission License 17/4/AEL/MP312/11/07

GENERAL MANAGER

2023/01/09


DATE



SEPTEMBER 2022

DUVHA POWER STATION MONTHLY EMISSIONS REPORT

Atmospheric Emission License 17/4/AEL/MP312/11/07



1 RAW MATERIALS AND PRODUCTS

Raw Materials	Raw Material Type	Units	Maximum Permitted Consumption Rate	Consumption Rate Sep-2022
and Products	Coal	Tons	1 400 000	337 054.53
	Fuel Oil	Tons	5 000	2172.03
	Product / By- Product Name	Units	Maximum Production Capacity Permitted	Production Rate Sep 2022
Production		Units		Production Rate Sep 2022 601.06
Production Rates	Product Name		Capacity Permitted	2022

2 ENERGY SOURCE CHARACTERISTICS

Coal Characteristic	Units	Stipulated Range	Monthly Average Content	
Sulphur Content	%	0.6 TO >1.2	0.91	
Ash Content	%	27 TO 30	26.46	

3 EMISSION LIMITS (mg/Nm³)

Associated Unit/Stack	PM	SOx	NOx
Unit 1	100	3500	1100
Unit 2	100	3500	1100
Unit 3	100	3500	1100
Unit 4	100	3500	1100
Unit 5	100	3500	1100
Unit 6	100	3500	1100

4 ABATEMET TECHNOLOGY (%)

Associated Unit/Stack	Technology Type	Efficiency Sep-2022	Technology Type	SO3 Utilization Sep-2022
Unit 1	FFP	99.9%	n/a	n/a
Unit 4	ESP + SO₃	99.2%	SO₃	98.7%
Unit 5	ESP + SO ₃	99.3%	SO ₃	95.6%

Note: ESP plant does not have bypass mode operation, hence plant 100% Utilised.

5 MONITOR RELIABILITY (%)

Associated Unit/Stack	PM	SO ₂	NO
Unit 1	91.7	99.8	99.8
Unit 4	94.2	99.4	99.5
Unit 5	100.0	99.8	100.0

Note: NOx emissions is measured as NO in PPM. Final NOx value is expressed as total NO2

6 EMISSION PERFORMANCE

Table 6.1: Monthly tonnages for the month of September 2022

Associated Unit/Stack	PM (tons)	SO ₂ (tons)	NO _x (tons)	
Unit 1	17.0	2 751	1 513	
Unit 4	216.5	2 316	1 235	
Unit 5	178.5	2 110	936	
SUM	411.97	7 177	3 684	

Table 6.2: Operating days in compliance to PM AEL Limit - September 2022

Associated Unit/Stack	Normal	Grace	Section 30	Contravention	Total Exceedance	Average PM (mg/Nm³)
Unit 1	22	0	0	0	0	12.3
Unit 4	16	6	0	0	6	159.6
Unit 5	8	9	0	2	-11	145.9
SUM	46	15	0	0	17	

Table 6.3: Operating days in compliance to SOx AEL Limit - September 2022

Associated Unit/Stack	Normal	Grace	Section 30	Contravention	Total Exceedance	Average SOx (mg/Nm³)
Unit 1	24	0	0	0	0	1 658.2
Unit 4	26	0	0	0	0	1 530.3
Unit 5	22	0	0	0	0	1 622.2
SUM	72	0	0	0	0	


Table 6.4: Operating days in compliance to NOx AEL Limit - September 2022


Associated Unit/Stack	Normal	Grace	Section 30	Contravention	Total Exceedance	Average NOx (mg/Nm³)
Unit 1	24	0	0	0	0	880.9
Unit 4	26	0	0	0	0	796.2
Unit 5	22	0	0	0	0	718.7
SUM	72	0	0	0	0	


Note: NOx emissions is measured as NO in PPM. Final NOx value is expressed as total NO2


Table 6.5: Legend Description


Condition	Colour	Description			
Normal		Emissions below Emission Limit Value (ELV)			
Grace		Emissions above the ELV during grace period			
Section 30		Emissions above ELV during a NEMA S30 incident			
Contravention		Emissions above ELV but outside grace or S30 incident conditions			























7 SHUT DOWN AND LIGHT UP INFORMATION

Tables 7.1: Shut-down and light-up information for the month of September 2022

Unit No.1	Ev	ent 1	Ev	ent 2	E	vent 3	Ev	ent 4
Breaker Open (BO)	7:00 pm	2022/09/07	2:25 am	2022/09/12	7:15 am	2022/09/17	12:50 am	2022/09/19
Draught Group (DG) Shut Down (SD)	9:05 pm	2022/09/07	2:25 am	2022/09/12	DG did not trip or SD	DG did not trip or SD	12:55 am	2022/09/19
BO to DG SD (duration)	00:02:05	DD:HH:MM	00:00:00	DD:HH:MM	n/a	DD:HH:MM	00:00:05	DD:HH:MM
Fires in time	4:50 am	2022/09/09	3:00 am	2022/09/12			11:25 am	2022/09/25
Synch. to Grid (or BC)	9:05 am	2022/09/09	5:10 am	2022/09/12			8:30 pm	2022/09/25
Fires in to BC (duration)	00:04:15	DD:HH:MM	00:02:10	DD:HH:MM		DD:HH:MM	00:09:05	DD:HH:MM
Emissions below limit from BC (end date)	not > limit	not > limit	not > limit	not > limit			not > limit	not > limit
Emissions below limit from BC (duration)	n/a	DD:HH:MM	n/a	DD:HH:MM		DD:HH:MM	n/a	DD:HH:MM

Unit No.4	Ev	ent 1	Event 2		
Breaker Open (BO)	9:10 pm	2022/09/04	7:15 am	2022/09/17	
Draught Group (DG) Shut Down (SD)	10:15 am	2022/09/05	DG did not trip or SD	DG did not trip or SD	
BO to DG SD (duration)	00:13:05	DD:HH:MM	n/a	DD:HH:MM	
Fires in time	3:45 pm	2022/09/11			
Synch. to Grid (or BC)	8:40 am	2022/09/12			
Fires in to BC (duration)	00:16:55	DD:HH:MM		DD:HH:MM	
Emissions below limit from BC (end date)	12:00 am	2022/09/15			
Emissions below limit from BC (duration)	02:15:20	DD:HH:MM		DD:HH:MM	

Unit No.5	Event 1		
Breaker Open (BO)	7:40 pm	2022/09/14	
Draught Group (DG) Shut Down (SD)	1:00 am	2022/09/15	
BO to DG SD (duration)	00:05:20	DD:HH:MM	
Fires in time	9:25 am	2022/09/23	
Synch. to Grid (or BC)	11:25 am	2022/09/23	
Fires in to BC (duration)	00:02:00	DD:HH:MM	
Emissions below limit from BC (end date)	12:00 am	2022/09/28	
Emissions below limit from BC (duration)	04:12:35	DD:HH:MM	

8. GENERAL

Units 2, 3 and 6 were offload during the month of September 2022.

Exceedances

Unit 4:

13-14/09/2022

Cold unit light up.

19/09/2022

Hot unit light up

21/09/2022

- SO3 plant tripped due to power supply trip.
- Dust Handling plant righthand aeroslide heater temperature was Low.

26/09/2022

• Electrostatic Precipitator fields 2.3 left hand and 3.3 right hand were not in service while field 4.5 was underperforming.

30/09/2022

High back-end temperatures after sootblowing conducted. This was due to the low availability of the Sootblowers.

Unit 5:

03-04/09/2022

- SO3 plant went on hold mode and was not injecting sulphur.
- High backend temperatures due to ineffective Sootblowers

06-09/09/2022

The 48 hours allowable for upset conditions were exceeded from the 08th to the 09th of September 2022 in unit 5. The final investigation reports will be submitted to your office before the 31st of October 2022.

14/09/2022

High back-end temperatures after sootblowing conducted. This was due to the low availability of the Sootblowers.

24-29/09/2022

Contravention incident: The 72 Hours allowable for a cold unit light up were exceeded at Duvha Unit 5 from the 27th of September 2022 to the 03rd of October 2022. A detailed investigation report with root cause and preventative actions will be submitted to your office once completed.

The averages Oxygen(O2) and Carbon Dioxide (CO2) data from the QAL 2 tests reports were used for reporting for Units 1, 5 and 6 due to poor performance of the O2 and CO2 gaseous monitors. These poor performances of the gaseous monitors were identified to be caused by the incorrect installation of O2 analyser. An action is being implemented to relocate all the units' O2 monitors to their own measurement port. This action will be completed no later than 31 December 2022.

The rest of the information demonstrating compliance with the emission license conditions is supplied in the annual emission report which will be sent to your office.

9 & 10 Complaints and S30 Incidents

Register

Refer to addendum A

Boller Plant Engineering

Manager-

Engineering Manager

Manager

Environmental

Date

Compiled by:

Environmental Officer

For:

Nkangala District Municipality Air Quality Officer

Copies:

Generation Environmental

Management

D Herbst B

Mccourt

Generation Compliance Management

Management Generation Asset Management R

Rampiar

E Patel

Duvha Power Station:

Engineering Manager Operating Manager Maintenance Manager Production Manager

Boiler Engineering Manager

System Engineer

Environmental Manager

ADDENDUM TO MONTHLY EMISSIONS REPORT

9 COMPLAINTS REGISTER

Table 9. Complaints for the month of September 2022

Source Code / Name	Root Cause Analysis	Calculation of Impacts / emissions associated with the incident
No complaints were rece	ved during the month of September 2022.	*

10 S30 INCIDENT OR LEGAL CONTRAVENTION REGISTER

To be completed in the case of a S30 incident or a legal contravention:

Unit no	Incident Start Date	Incident End Date	Incident Cause	Remedial action	S30 initial notification sent	Date S30 investigation report sent	Date DEA Acknowledgment	Date DEA Acceptable	Comments / Reference No.
Unit 5	08/09/2022	09/09/2022	Incident still und	ler investigation	09/09/2022	Incident still under investigation. Preliminary investigation report submitted to your office once completed 22/09/2022	Not yet acknowledged	N/A	(14/7/6/2/4/2/2222- IDFF380892022
Unit 5	27/09/2022	03/10/2022	Incident still und	ler investigation			ported as a Section 3	0.	Contravention incident: The 72 Hours allowable for a cold unit light up were exceeded at Duvha Unit 5 from the 27 th of September 2022 to the 03 rd of October 2022. A detailed investigation report

	with root cause and preventative actions will be submitted to your office once completed.
--	---