



CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST

Template Identifier	240-43821898	3
Document Identifier	WFM/LD - 45.5003	0
Authorisation Date	22-Nov-12	
Review Date	01-Nov-15	

NO	ENVIRONMENTAL ASPECTS	CONFORMANCE NOT CONFORMING COMMENTS	CORRECTIVE ACTION	CONDITION/ CLAUSE	% RATING
Environmental Policy/ Environmental Management Plan (EMP) and Environmental Authorisation (EA) Training/Awareness					
Has EA_EMP been communicated to an agent, sub-contractor, employee or any person rendering a service to the holder of the authorisation? This includes the Eskom SHEQ Policy and must be displayed.					
Planning - Environmental Aspects					
Working Areas					
Have construction activities remained within the designated working areas?					
1. Inform the contractor about the no go areas/work restrictions i.e. sensitive vegetation/species and watercourses etc.					
2. Is the housekeeping done neatly i.e. stockpiling of materials & equipment's etc.					
3. Are vehicles parked in their demarcated parking areas?					
4. Are working areas well defined with a					

**CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST**

		Template Identifier	240-4392-1898	3
		Document Identifier	WFN00D - 4.5.5003	0
		Authorisation Date	22-Nov-12	
		Review Date	01-Nov-15	
fence or danger tape, in case of powerline, the servitude width 18m for 11 – 22kV and 45m for 132kV				
Property Access and Camp Establishment				
Was permission obtained from the property owners before construction commence?				
6.				
Do the property owners have unrestricted access to their property?				
7.				
Are all access roads and camp establishment created with the assistance of ECO /Botanist /Freshwater Specialist or Site Engineer? If applicable		Existing roads used track with assistance from landowners.		
8.				
Were entrance gates, walls, paths, roads and fence rehabilitated satisfactorily as per EA-EMP conditions i.e. landowners		To be assessed towards end of construction.		
9.				
Vegetation Management				
Are applicable permits available for indigenous vegetation clearance,		N/A		
10.				
cutting, disturbing, damaging or trimming of protected/endangered trees and monumental trees as per				
				N/A



CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST

Template Identifier	240-43921888	3
Document Identifier	WFMLD - 4.5.5603	0
Authorisation Date	22-Nov-12	
Review Date	01-Nov-15	

applicable SAHRA and City Bylaws acts?			
Is the servitude or working area cleared of alien vegetation as per 32- 247 Standard for Bush Clearance and maintenance within overhead Powerline servitude procedure i.e. firebreak	Part 3 & 4. removed between Str. 3 & 4.		/
Have all bush clearing and herbicide methods been undertaken under the supervision of a registered Pest Control Officer (PCO) i.e. produce valid letter from DAFF	Y. S Gxwawebi		/
Clearance of vegetation in Critical Biodiversity Areas (CBA) must be done with an approved method statement by the ECO and or specialist recommendation as per EA i.e. site, area, height and timing	N/A		N/A
Spillages			
Is there a stock of adequate oil spill remediation kit i.e. oil spill kit			/
14.			

CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST		Template Identifier	240-43921898	3
		Document Identifier	WFMILD - 4.5.5003	0
		Authorisation Date	22-Nov-12	
		Review Date	01-Nov-15	
15. Have any spill/leak occurred on site i.e. oil, chemical, diesel, paint, sewer and waste water. Are the spills/leaks visible from construction site				
16. Have the spills been managed according to Western Cape Operating Unit Oil Spill Management Instruction reference no. 240-79588150.		N/A		
Natural Heritage Resources				
17. Were there any tribal graves, archaeological and paleontological sites identified before or during the construction activities?		N		
18. If yes, was construction stopped and the ECO contacted immediately?		N/A		
19. Was the Heritage Resource Agency or a Heritage Specialist contacted immediately?		N/A		
Portable Toilet/Sanitation				
20. Are there sufficient portable toilets i.e. 1:8 - 10 people and within walking distance				
21. Portable toilets to be serviced weekly i.e. clean, smell good, toilet roll & soap #:		Service 17/3/2015 Sop #: 8323	Two toilets on site need to be serviced.	



CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST

Template Identifier	240-43921898	3
Document Identifier	WFM/LD - 4.5.5003	0
Authorisation Date	22-Nov-12	
Review Date	01-Nov-15	

functional at all times. Services receipts available		
Sanitation and ablution facilities should not result in an impact on the environment? Sewage spillage etc.	N	1
Integrated Waste Management		
Is there an integrated waste management system in place i.e. intervals for waste disposal, bins labelled accordingly, proper waste storage and tightly contained, waste separation and recycling etc.	Y	1
Are there sufficient waste bins on site?	Y	1
Was litter noted during site inspection?	N	1
Waste Manifest, Safe disposal certificate from the landfill site and Letter of agreement from the Municipality to comply with Waste General Notice (GN) No. 435 of 2011, Annexure 1 & 2. All other provisions of NEM:WA to be complied with if	Econoco slips & Morereesburg corpora.	1

 Eskom CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST		Template Identifier 43921898 WFWILD - 3 Document Identifier 4.5.5/003 Authorisation Date 22-Nov-12 Review Date 01-Nov-15
	applicable.	
27.	Are the hazardous and non-hazardous products (paints, paste, chemicals etc.) labelled and have Material Safety Data Sheet (MSDS)?	<input checked="" type="checkbox"/> In fire shed. <input checked="" type="checkbox"/>
Additional Environmental Aspects		
28.	Are there trained fire fighter and adequate fire-fighting equipment in appropriate places i.e. valid fire extinguisher	<input checked="" type="checkbox"/>
29.	Are there effective dust control (if necessary) measures in place.	<input checked="" type="checkbox"/> Not an issue
30.	Are there noise control (if necessary) measures in place.	<input checked="" type="checkbox"/> Not an issue
31.	Are there any erosion control (if necessary) measures in place?	<input checked="" type="checkbox"/> No erosion issue
32.	Are there top soil management in place i.e. separation of top soil vs. sub-soil, backfilling and levelling (if necessary)	<input checked="" type="checkbox"/> All backfilled.
33.	Is there any impact on the water resource - wetland, stormwater drain, river, stream, lake, dam and riparian	<input checked="" type="checkbox"/>



CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST

Template Identifier	240-43921898	3
Document Identifier	WFMILD - 4.5.5003	0
Authorisation Date	22-Nov-12	
Review Date	01-Nov-15	

vegetation?				
Implementation and Operation - Resources, Roles, Responsibility and Authority				
Have environmental Roles and Responsibilities been assigned to relevant personnel? One (1) person to be appointed per team?	✓ . Anton West & Morris Mngwetwa.			/
Communication				
Has the Environmental Emergency Preparedness and Response (EEPR) procedure (WPC020) being communicated to everyone on site?	✓ . During EEP training.			/
Have the non-conformance report (NCR), Incidents and any other deviations being communicated to the project team?	✓ . 5131205			/
Has the contractor conducted weekly environmental awareness/toolbox sessions? Keep a signed attendance register.	✓ . S131205: Gates			/
Have the relevant aspects of the Eskom procedures and instruction been communicated?	✓ . 151912014			/
Documentation - Control of Documents				
Are there Eskom Procedures on file	✓			/
39.				

Eskom		CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST		Template Identifier	240-43921898	3	
		Document Identifier	WFMILD - 4.5.5003	Authorisation Date	22-Nov-12	Review Date	01-Nov-15
such as Waste Standards, Bush Clearing procedure and Oil Spill Instruction etc.?							
Environmental Emergency Preparedness and Response procedure (EPR)							
Are the emergency numbers available 40. and up-to-date to all construction personnel?	Y						
Is there an Environmental Emergency preparedness Procedure to deal with environment-related incidents (e.g. fires, oil spillages, snakes bites, bee stings etc.)? Eskom EPR procedure to be available and displayed on site.	Use Eskom EPR. Y						
Checking - Non Conformity and Corrective Action Plan							
Has there been any deviation from the requirements of EA-EMP, Permit, License, RoD and any other conditions or agreement?	N						
If any deviations, have they been reported to Environmental Officer/Clerk of Works/Project Coordinator/Site Manager within 24 Hours e.g. oil & diesel spillages etc.	Y						
Have the action plans been developed	Y						



CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST

Template Identifier	240-43921596	3
Document Identifier	WFMLD - 4.5.51003	0
Authorisation Date	22-Nov-12	01-Nov-15

<p style="text-align: center;">(6)</p> <p>and incidents addressed adequately? Shall not exceed more than 24 Hours depending on the incident or action?</p>		
45.	Have all the Non Conformances Reports been addressed and closed e.g. complaints, <u>incidents</u> , pollution etc? If applicable	<input checked="" type="checkbox"/>
<p>Control of Records</p> <p>Does the site have Environmental File with EA_EMP and Training records, Incidents Flash Reports, Permits, Licences, RoD, Waste Manifest, Letter of consent, NCR, Inventory of Incidents, Complaints Register, Action Plans and Audit Reports? To be produced when required at all times.</p>		
<p>Internal Audits</p> <p>Has the contractor performed a self-audit and addressed all deviations?</p> <p>47. Atleast one or more in two weeks?</p>		
	Y . 24/3/2015	/

	CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST		
	Template Identifier	240-43921898	3
	Document Identifier	WFNLD - 0	0
	Authorisation Date	22-Nov-12	
	Review Date	01-Nov-15	

PROJECT DETAILS			
Name of the Project : Powerline or Substation	Moersburg-Uggenhu	Name of the Auditor	M. Hendrikse
Name of the Construction Representative	Chris Matthee	Date	26/3/2015
Signature		Signature	

COMPLIANCE STATUS

Number of Compliance	46	5
Number of Non-Conformance	0	5
Compliance Rating:	Compliant	X
Risk of non-compliant		
Non-Compliant		
Percentage Compliance Score	99%	

- 96: ✓ aggregate to be removed.
- 97: ✓ aggregate to be removed.
- 98: ✓ aggregate to be removed.
- 99: ✓ aggregate to be removed.
- 100: ✓ aggregate to be removed.
- 101: ✓ aggregate to be removed.
- 102: ✓ aggregate to be removed.
- 103: ✓ aggregate to be removed.
- 104: ✓ aggregate to be removed.
- 105: ✓ aggregate to be removed.
- 106: ✓ aggregate to be removed.
- 107: ✓ aggregate to be removed.
- 108: ✓ aggregate to be removed.
- 109: ✓ aggregate to be removed.
- 110: ✓ aggregate to be removed.
- 111: ✓ aggregate to be removed.
- 112: ✓ aggregate to be removed.
- 113: ✓ aggregate to be removed.
- 114: ✓ aggregate to be removed.
- 115: ✓ aggregate to be removed.
- 116: ✓ aggregate to be removed.
- 117: ✓ aggregate to be removed.
- 118: ✓ aggregate to be removed.
- 119: ✓ aggregate to be removed.
- 120: ✓ aggregate to be removed.
- 121: ✓ aggregate to be removed.
- 122: ✓ aggregate to be removed.
- 123: ✓ aggregate to be removed.
- 124: ✓ aggregate to be removed.
- 125: ✓ aggregate to be removed.
- 126: ✓ aggregate to be removed.
- 127: ✓ aggregate to be removed.
- 128: ✓ aggregate to be removed.
- 129: ✓ aggregate to be removed.
- 130: ✓ aggregate to be removed.
- 131: ✓ aggregate to be removed.
- 132: ✓ aggregate to be removed.
- 133: ✓ aggregate to be removed.
- 134: ✓ aggregate to be removed.
- 135: ✓ aggregate to be removed.
- 136: ✓ aggregate to be removed.
- 137: ✓ aggregate to be removed.
- 138: ✓ aggregate to be removed.
- 139: ✓ aggregate to be removed.
- 140: ✓ aggregate to be removed.
- 141: ✓ aggregate to be removed.
- 142: ✓ aggregate to be removed.
- 143: ✓ aggregate to be removed.
- 144: ✓ aggregate to be removed.
- 145: ✓ aggregate to be removed.
- 146: ✓ aggregate to be removed.
- 147: ✓ aggregate to be removed.
- 148: ✓ aggregate to be removed.
- 149: ✓ aggregate to be removed.
- 150: ✓ aggregate to be removed.
- 151: ✓ aggregate to be removed.
- 152: ✓ aggregate to be removed.
- 153: ✓ aggregate to be removed.
- 154: ✓ aggregate to be removed.
- 155: ✓ aggregate to be removed.
- 156: ✓ aggregate to be removed.
- 157: ✓ aggregate to be removed.
- 158: ✓ aggregate to be removed.
- 159: ✓ aggregate to be removed.
- 160: ✓ aggregate to be removed.
- 161: ✓ aggregate to be removed.
- 162: ✓ aggregate to be removed.
- 163: ✓ aggregate to be removed.
- 164: ✓ aggregate to be removed.
- 165: ✓ aggregate to be removed.
- 166: ✓ aggregate to be removed.
- 167: ✓ aggregate to be removed.
- 168: ✓ aggregate to be removed.
- 169: ✓ aggregate to be removed.
- 170: ✓ aggregate to be removed.
- 171: ✓ aggregate to be removed.
- 172: ✓ aggregate to be removed.
- 173: ✓ aggregate to be removed.
- 174: ✓ aggregate to be removed.
- 175: ✓ aggregate to be removed.
- 176: ✓ aggregate to be removed.
- 177: ✓ aggregate to be removed.
- 178: ✓ aggregate to be removed.
- 179: ✓ aggregate to be removed.
- 180: ✓ aggregate to be removed.
- 181: ✓ aggregate to be removed.
- 182: ✓ aggregate to be removed.
- 183: ✓ aggregate to be removed.
- 184: ✓ aggregate to be removed.
- 185: ✓ aggregate to be removed.
- 186: ✓ aggregate to be removed.
- 187: ✓ aggregate to be removed.
- 188: ✓ aggregate to be removed.
- 189: ✓ aggregate to be removed.
- 190: ✓ aggregate to be removed.
- 191: ✓ aggregate to be removed.
- 192: ✓ aggregate to be removed.
- 193: ✓ aggregate to be removed.
- 194: ✓ aggregate to be removed.
- 195: ✓ aggregate to be removed.
- 196: ✓ aggregate to be removed.
- 197: ✓ aggregate to be removed.
- 198: ✓ aggregate to be removed.
- 199: ✓ aggregate to be removed.
- 200: ✓ aggregate to be removed.