



CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST

Template Identifier	240-43921698	3
Document Identifier	WFMLD - 4.5.5003	0
Authorisation Date	22-Nov-12	
Review Date	01-Nov-15	

NO	ENVIRONMENTAL ASPECTS	CONFORMANCE NOT CONFORMANCE STATEMENTS	CORRECTIVE ACTION	CONDITION/ CLAUSE	% RATING
Environmental Policy					
Environmental Management Plan (EMP) and Environmental Authorisation (EA) Training/Awareness					
1.	Has EA_EMP been communicated to an agent, sub-contractor, employee or any person rendering a service to the holder of the authorisation? This includes the Eskom SHEQ Policy and must be displayed.	Y . SPP existing contract as on 14/2015.		1	
Planning - Environmental Aspects					
Working Areas					
2.	Have construction activities remained within the designated working areas?	Y .		1	
3.	Inform the contractor about the no go areas/work restrictions i.e. sensitive vegetation/species and watercourses etc.			1	
4.	Is the housekeeping done neatly i.e. stockpiling of materials & equipment's etc.	Y .		1	
5.	Are vehicles parked in their demarcated parking areas?	Y .		1	
6.	Are working areas well defined with a barrier in service?	Y .		1	



CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST


Template Identifier	240-43921888	3
Document Identifier	WFM/LD - 4.5.5/003	0
Authorisation Date	22-Nov-12	
Review Date	01-Nov-15	

fence or danger tape, in case of powerline, the servitude width 18m for 11 - 22kV and 45m for 132kV	tudue & existing access roads has indicated by formers			
Property Access and Camp Establishment				
Was permission obtained from the property owners before construction commence?	Y. Registered servitudes & land owner permissions.			
Do the property owners have unrestricted access to their property?	Y.			
Are all access roads and camp establishment created with the assistance of ECO /Botanist /Freshwater Specialist or Site Engineer? If applicable	Y. ECO & farmers			
Were entrance gates, walls, paths, roads and fence rehabilitated satisfactorily as per EA-EMP conditions i.e. landowners	To be assessed & done closed to end of construction			
Vegetation Management				
Are applicable permits available for indigenous vegetation clearance, cutting, disturbing, damaging or trimming of protected/endangered trees and monumental trees as per	N/A - No protected vegetation			N/A



CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST

		Template Identifier	240-43921898	3
		Document Identifier	WFMFLD - 4.5.5003	0
		Authorisation Date	22-Nov-12	
		Review Date	01-Nov-15	
1.	applicable SAHRA and City Bylaws acts?			
2.	Is the servitude or working area cleared of alien vegetation as per 32-247 Standard for Bush Clearance and maintenance within overhead powerline servitude procedure i.e. firebreak	Y		
3.	Have all bush clearing and herbicide methods been undertaken under the supervision of a registered Pest Control Officer (PCO) i.e. produce valid letter from DAFF	Y. Piko Investments applied herbicides & stocked cut wood on boundary of servitude.		
4.	Clearance of vegetation in Critical Biodiversity Areas (CBA) must be done with an approved method statement by the ECO and or specialist recommendation as per EA i.e. site, area, height and timing	N/A. No CBA.		
5.	Spillages			
6.	Is there a stock of adequate oil spill remediation kit i.e. oil spill kit	Y. Two wheelie bins @ camp & kits on trucks @ site.		1



CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST

Template Identifier	240-43921898	3
Document Identifier	WFMLD - 4.5.5003	0
Authorisation Date	22-Nov-12	
Review Date	01-Nov-15	

Have any spill/leak occurred on site i.e. oil, chemical, diesel, paint, sewer and waste water. Are the spills/leaks visible from construction site	N	1
Have the spills been managed according to Western Cape Operating Unit Oil Spill Management Instruction reference no. 240-79588150.	N/A	N/A
Natural Heritage Resources		
Were there any tribal graves, archaeological and paleontological sites identified before or during the construction activities?	N	1
If yes, was construction stopped and the ECO contacted immediately?	N/A	N/A
Was the Heritage Resource Agency or a Heritage Specialist contacted immediately?	N/A	N/A
Portable Toilet/Sanitation		
Are there sufficient portable toilets i.e. 1:8 - 10 people and within walking distance	4 & Four	1
Portable toilets to be serviced weekly i.e. clean, smell good, toilet roll &	4, 3rd & 2015, 23rd & 2015, 16th & 2015, 01st & 2015.	1



CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST

Template Identifier	240-43921698	3
Document Identifier	WFM/LD - 4.5.5/003	0
Authorisation Date	22-Nov-12	
Review Date	01-Nov-15	

functional at all times. Services receipts available			
Sanitation and ablution facilities			
22. should not result in an impact on the environment? Sewage spillage etc.	N		
Integrated Waste Management			
Is there an integrated waste management system in place i.e. intervals for waste disposal, bins labelled accordingly, proper waste storage and tightly contained, waste separation and recycling etc.	Y		
Are there sufficient waste bins on site?	Y. Bins for various waste streams.		1
Was litter noted during site inspection?	N		1
Waste Manifest, Safe disposal certificate from the landfill site and Letter of agreement from the Municipality to comply with Waste General Notice (GN) No. 435 of 2011, Annexure 1 & 2. All other provisions of NEM:WA to be complied with if full.	Y. Recycled @Zingai on 6/15/2015 & 14/4/2015. Skip not full yet. To be taken to UKHSEKWE when full.		1



CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST


		Template Identifier 43921898	240-3
		Document Identifier WFM/LD - 0 4.5.5/003	
		Authorisation Date 22-Nov-12	
		Review Date 01-Nov-15	
	applicable.		
27.	Are the hazardous and non-hazardous products (paints, paste, chemicals etc.) labelled and have Material Safety Data Sheet (MSDS)?		
Additional Environmental Aspects			
28.	Are there trained fire fighter and adequate fire-fighting equipment in appropriate places i.e. valid fire extinguisher		
29.	Are there effective dust control (if necessary) measures in place.	No issues	
30.	Are there noise control (if necessary) measures in place.	No issues	
31.	Are there any erosion control (if necessary) measures in place?	No issues	
32.	Are there top soil management in place i.e. separation of top soil vs. sub-soil, backfilling and levelling (if necessary)	All backfilled.	
33.	Is there any impact on the water resource - wetland, stormwater drain, river, stream, lake, dam and riparian	N. Compliance to GA.	



CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST

Template Identifier	240-43921898	3
Document Identifier	WFMILD - 4.5.5003	0
Authorisation Date	22-Nov-12	
Review Date	01-Nov-15	

vegetation?				
Implementation and Operation - Resources, Roles, Responsibility and Authority				
Have environmental Roles and Responsibilities been assigned to relevant personnel? One (1) person to be appointed per team?	<input checked="" type="checkbox"/> . Done & ticked			
Communication				
Has the Environmental Emergency Preparedness and Response (EEPR) procedure (WPC020) being communicated to everyone on site?	<input checked="" type="checkbox"/> . During Env training.			
Have the non-conformance report (NCR), Incidents and any other deviations being communicated to the project team?	<input checked="" type="checkbox"/> No issues. N/A			
Has the contractor conducted weekly environmental awareness/toolbox sessions? Keep a signed attendance register.	<input checked="" type="checkbox"/> 21/4/2015, 15/4/2015 14/4/2015.			
Have the relevant aspects of the Eskom procedures and instruction been communicated?	<input checked="" type="checkbox"/> During Env training.			
Documentation - Control of Documents				
Are there Eskom Procedures on file	<input checked="" type="checkbox"/>			



CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST

		Template Identifier	240-43921898	3
		Document Identifier	WFM/LD - 4.5.5/003	0
		Authorisation Date	22-Nov-12	
		Review Date	01-Nov-15	
such as Waste Standards, Bush Clearing procedure and Oil Spill Instruction etc.?				
Environmental Emergency Preparedness and Response procedure (EPR)				
Are the emergency numbers available 40. and up-to-date to all construction personnel?				
Is there an Environmental Emergency preparedness Procedure to deal with environment-related incidents (e.g. fires, oil spillages, snakes bites, bee stings etc.)? Eskom EPR procedure to be available and displayed on site.		1. Weld fire mock drill performed on 4/15/2015.		
Checking - Non Conformity and Corrective Action Plan				
Has there been any deviation from the requirements of EA-EMP, Permit, License, RoD and any other conditions or agreement?		N/A	Ensure compliance to the method statement or advice of deviations needed.	
If any deviations, have they been reported to Environmental Officer/Clerk of Works/Project Coordinator/Site Manager within 24 Hours e.g. oil & diesel spillages etc.		N/A	N/A	
44. Have the action plans been developed		N/A	N/A	



CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST

Template Identifier	240-43921698	3
Document Identifier	WFMLD - 4.5.51003	0
Authorisation Date	22-Nov-12	
Review Date	01-Nov-15	

and incidents addressed adequately?		
Shall not exceed more than 24 Hours depending on the incident or action?		
Have all the Non Conformances Reports been addressed and closed	No issues.	N/A
45. e.g. complaints, incidents, pollution etc? If applicable		
Control of Records		
Does the site have Environmental File with EA_EMP and Training records, Incidents Flash Reports, Permits, Licences, RoD, Waste Manifest, Letter of consent, NCR, Inventory of Incidents, Complaints Register, Action Plans and Audit Reports? To be produced when required at all times.	Y	1
Internal Audits		
Has the contractor performed a self audit and addressed all deviations?	Y. 8/14/2015 4/15/2015 15/14/2015.	1
47. Atleast one or more in two weeks?		

	CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST		
	Template Identifier	240-43921688	3
	Document Identifier	WFM/WLD - 4.5.5/003	0
	Authorisation Date	22-Nov-12	
	Review Date	01-Nov-15	

PROJECT DETAILS

Name of the Project : Powerline or Substation	Hoor Regensburg-Uggeni	Name of the Auditor	M. Hendrikus
Name of the Construction Representative	Lire: Loskoc	Date	6/5/2015
Signature	Dané Taubert	Signature	John

- o Strung from 4 - 42.
- o Bush preparing to string from 43. Truck were bush at site # 46.

COMPLIANCE STATUS

Number of Compliance	47
Number of Non-Conformance	47
Compliance Rating:	X
Risk of non-compliant	
Non-Compliant	
Percentage Compliance Score	100%.

- o method statement to be compiled for liliu crossing between structures 3 & 4. — made to do !