

Office audit @ comp site .



CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST

Template Identifier	240-43921998	3
Document Identifier	WFMILD - 4.5.5003	0
Authorisation Date	22-Nov-12	
Review Date	01-Nov-15	

NO	ENVIRONMENTAL ASPECTS	CONFORMING NON CONFORMING STATEMENTS	CORRECTIVE ACTION	CONDITION/ CLAUSE	% RATING
Environmental Policy					
	Environmental Management Plan (EMP) and Environmental Authorisation (EA) Training/Awareness				
Has EA_EMP been communicated to an agent, sub-contractor, employee or any person rendering a service to the holder of the authorisation? This includes the Eskom SHEQ Policy and must be displayed.					
		1. SITEQ policy displayed.		1	
Planning - Environmental Aspects					
	Working Areas				
	Have construction activities remained within the designated working areas?	Did not go to site.			
	Inform the contractor about the no go areas/work restrictions i.e. sensitive vegetation/species and watercourses etc.				N/A
	Is the housekeeping done neatly i.e. stockpiling of materials & equipment's etc.	Y			
	Are vehicles parked in their demarcated parking areas?	Y			
	Are working areas well defined with a	Did not go to site as			N/A

**CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST**


		Template Identifier	240-43921898	3
		Document Identifier	WFNLD - 4.5.5/003	0
		Authorisation Date	22-Nov-12	
		Review Date	01-Nov-15	
fence or danger tape, in case of powerline, the servitude width 18m for 11 - 22kV and 45m for 132kV		no activities on site		
Property Access and Camp Establishment				
Was permission obtained from the property owners before construction commence?		Y.	Tire land owner permission letters.	
Do the property owners have unrestricted access to their property?		Y.		
Are all access roads and camp establishment created with the assistance of ECO /Botanist /Freshwater Specialist or Site Engineer? If applicable		Y	& land owners.	
Were entrance gates, walls, paths, roads and fence rehabilitated satisfactorily as per EA-EMP conditions i.e. landowners		No issues.	To be assessed closer to end of construction	
Vegetation Management				
Are applicable permits available for indigenous vegetation clearance, cutting, disturbing, damaging or trimming of protected/endangered trees and monumental trees as per		N(f)		
10.				N(f).



CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST

Template Identifier	240-43921998	3
Document Identifier	WFMLD - 4.5.5003	0
Authorisation Date	22-Nov-12	
Review Date	01-Nov-15	

applicable SAHRA and City Bylaws acts?		
Is the servitude or working area cleared of alien vegetation as per 32- 247 Standard for Bush Clearance and maintenance within overhead Powerline servitude procedure i.e. firebreak	Y.	1
Have all bush clearing and herbicide methods been undertaken under the supervision of a registered Pest Control Officer (PCO) i.e. produce valid letter from DAFF	Y. Piko did bush-clearing between str. 3 & 4.	1
Clearance of vegetation in Critical Biodiversity Areas (CBA) must be done with an approved method statement by the ECO and or specialist recommendation as per EA i.e. site, area, height and timing	No CBA. N/A.	
Spillages		
Is there a stock of adequate oil spill remediation kit i.e. oil spill kit	Could not verify on trucks but two wheelie bins @ comp.	N/A.
14.		

**CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST**


		Template Identifier	240-43921898	3
		Document Identifier	WFM/LD - 4.5.5003	0
		Authorisation Date	22-Nov-12	
		Review Date	01-Nov-15	
15.	Have any spill/leak occurred on site i.e. oil, chemical, diesel, paint, sewer and waste water. Are the spills/leaks visible from construction site	N		1
16.	Have the spills been managed according to Western Cape Operating Unit Oil Spill Management Instruction reference no. 240-79588150.	N/A		
Natural Heritage Resources				
17.	Were there any tribal graves, archaeological and paleontological sites identified before or during the construction activities?	N		—
18.	If yes, was construction stopped and the ECO contacted immediately?	N/A		N/A
19.	Was the Heritage Resource Agency or a Heritage Specialist contacted immediately?	N/A		N/A
Portable Toilet/Sanitation				
20.	Are there sufficient portable toilets i.e. 1:8 - 10 people and within walking distance	Y. Toilets		1
21.	Portable toilets to be serviced weekly i.e. clean, smell good, toilet roll &	19/3/2015, 12/3/2015, 26/3/2015		1



CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST

Template Identifier	240-43921998	3
Document Identifier	WFM/LD - 4.5.5003	0
Authorisation Date	22-Nov-12	
Review Date	01-Nov-15	

	functional at all times. Services receipts available			
22.	Sanitation and ablution facilities should not result in an impact on the environment? Sewage spillage etc.	N		1
23.	Integrated Waste Management Is there an integrated waste management system in place i.e. intervals for waste disposal, bins labelled accordingly, proper waste storage and tightly contained, waste separation and recycling etc.	Y		1
24.	Are there sufficient waste bins on site?	Y		1
25.	Was litter noted during site inspection?	N		1
26.	Waste Manifest, Safe disposal certificate from the landfill site and Letter of agreement from the Municipality to comply with Waste General Notice (GN) No. 435 of 2011, Annexure 1 & 2. All other provisions of NEM:WA to be complied with if	Recycled waste on 27(3) 2015		1

**CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST**

Template Identifier	240-43921898	3
Document Identifier	WFM/LD - 4.5.5/003	0
Authorisation Date	22-Nov-12	
Review Date	01-Nov-15	

applicable.		
Are the hazardous and non-hazardous products (paints, paste, chemicals etc.) labelled and have Material Safety Data Sheet (MSDS)?	Y. Tr. Flammable cabinet @ site comp. MSDS register.	—
Additional Environmental Aspects		
Are there trained fire fighter and adequate fire-fighting equipment in appropriate places i.e. valid fire extinguisher	Y	—
Are there effective dust control (if necessary) measures in place.	No site activities today.	N/A
Are there noise control (if necessary) measures in place.	Y	N/A
Are there any erosion control (if necessary) measures in place?	No erosion concern	/
Are there top soil management in place i.e. separation of top soil vs. sub-soil, backfilling and levelling (if necessary)	All backfilled	/
Is there any impact on the water resource - wetland, stormwater drain, river, stream, lake, dam and riparian	Y	/



CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST

Template Identifier	240-43921898	3
Document Identifier	WFM/LD - 4.5.5/03	0
Authorisation Date	22-Nov-12	
Review Date	01-Nov-15	

vegetation?			
Implementation and Operation - Resources, Roles, Responsibility and Authority			
34.	Have environmental Roles and Responsibilities been assigned to relevant personnel? One (1) person to be appointed per team?	Y. Danne & Patrick.	
Communication			
35.	Has the Environmental Emergency Preparedness and Response (EEPR) procedure (WPC020) being communicated to everyone on site?	Y. During Emp Training.	
36.	Have the non-conformance report (NCR), Incidents and any other deviations being communicated to the project team?	N/A.	
37.	Has the contractor conducted weekly environmental awareness/toolbox sessions? Keep a signed attendance register.	Y. 31(3)ZS: Top Soil & Storage & use of oils	
38.	Have the relevant aspects of the Eskom procedures and instruction been communicated?	Y. During Emp Training.	
Documentation - Control of Documents			
39.	Are there Eskom Procedures on file	Y. See register	

 CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST		Template Identifier 43921898 Document Identifier WFM/LD - 0 Authorisation Date 22-Nov-12 Review Date 01-Nov-15
such as Waste Standards, Bush Clearing procedure and Oil Spill Instruction etc.?	Bush attached .	
Environmental Emergency Preparedness and Response procedure (EPR)		
Are the emergency numbers available and up-to-date to all construction personnel?	Y.	
40. Is there an Environmental Emergency preparedness Procedure to deal with environment-related incidents (e.g. fires, oil spillages, snakes bites, bee stings etc.)? Eskom EPR procedure to be available and displayed on site.	Y	
Checking - Non Conformity and Corrective Action Plan		
Has there been any deviation from the requirements of EA-EMP, Permit, License, RoD and any other conditions or agreement?	N.	
42. If any deviations, have they been reported to Environmental Officer/Clerk of Works/Project Coordinator/Site Manager within 24 Hours e.g. oil & diesel spillages etc.	N/A	
43. Have the action plans been developed	N/A	
44.		



CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST

Template Identifier	240-43821098	3
Document Identifier	WF-MLD - 4.5.5003	0
Authorisation Date	22-Nov-12	
Review Date	01-Nov-15	

and incidents addressed adequately? Shall not exceed more than 24 Hours depending on the incident or action?		
Have all the Non Conformances Reports been addressed and closed e.g. complaints, incidents, pollution etc? If applicable	N/A	N/A
Control of Records		
Does the site have Environmental File with EA_EMP and Training records, Incidents Flash Reports, Permits, Licences, RoD, Waste Manifest, Letter of consent, NCR, Inventory of Incidents, Complaints Register, Action Plans and Audit Reports? To be produced when required at all times.	Y	① Update incident register in #17 of file.
Internal Audits		
Has the contractor performed a self-audit and addressed all deviations? At least one or more in two weeks?	Y. 31/3/2015 4/3/2015	1

	CONSTRUCTION ENVIRONMENTAL AUDIT CHECKLIST		
	Template Identifier	240-43921888	3
	Document Identifier	WFNWLDA-4.5.5003	0
	Authorisation Date	22-Nov-12	
	Review Date	01-Nov-15	

PROJECT DETAILS			
Name of the Project : Powerline or Substation	Moersburg-Ugwele	Name of the Auditor	M. Hendriks
Line : Posten		Date	7/14/2015
Name of the Construction Representative		Signature	
Signature			

COMPLIANCE STATUS			
Number of Compliance			
Number of Non-Conformance			
Compliance Rating:	Compliant	Risk of non-compliant	
Non-Compliant			
Percentage Compliance Score			

Mooresburg-Vryheid Line: Roskom 7/4/2015

Checklist of Documents Requirements for Construction Site

1 Environmental Authorisation	✓	29/11/2010
2 Environmental Management Plan	✓	07/12/2010
3 Permit/Licence/RoD e.g. Water or vegetation permits	✓	
4 Construction Environmental Audit Checklist		
5 Agreement letters:		
waste		
sewage		
drinking water	✓	
construction water	✓	
laydown areas		
parking areas		
camp site		
accommodation		
land owner	✓	
Environmental, Occupational Health and Safety Incident	✓	
6 Management Procedure - 32- 95	✓	
VEGETATION MANAGEMENT AND MAINTENANCE WITHIN ESKOM LAND SURNITIUTES AND RIGHTS OF WAY - 32- 247	Jan '14	✓
Access to Farms (including strategy on dealing with Game Farms)- 34 - 190	March '10	✓
Safety, Health, Environment and Quality (SHEQ) Policy - 32 - 727	Aug '16	✓
Environmental Emergency Preparedness and Response - WPC020	Nov '16	✓
11 Land and biodiversity standard - 32 - 815	Nov '16	✓
12 Land and Biodiversity Policy - 32 - 736	Nov '16	✓
Management of Protected and Indigenous Vegetation - WTB003	Nov '16	✓
Eskom Dx Western Cape Operating Unit - Waste Management Plan (WMP) - 2013 Rev 3		✓
15 Eskom Waste Management Standard - 32 - 245	July '15	✓
16 Water Management Policy - 32 - 1163	May '16	✓
17 Environmental Complaints/Query Register - WPC-008		✓
18 Oil Spill Management Instruction - 240-79588150	Nov '17	✓
19 Project Audit and EMP Training Schedule		✓
20 Transportation of hazardous goods 240-79588146	May '14	✓
Environmental Management Systems for distribution WCCU	Nov '17	✓
In Accordance with ISO14001 - 240-7773132	Nov '17	✓
Environmental training, awareness and competence procedure in accordance with ISO14001 environmental Management Systems requirements - 240-83895653	Aug '17	✓

GFA, waste license: Zingari waste recovery, WWTP license,
Visserfont waste license, mining permits, JHO method
statement.

Tip Trans on 27/11/2014

G.Carspers on 28/01/2015

Soil : G.Carspers on 9/2/2015

Five landowners

To be updated.
Appointments sent

