

## APPENDIX A: MICROHABITATS



Figure1: Natural grassland in the study area near Kendal



Figure 2: A dam in the study area

## APPENDIX A: MICROHABITATS



Figure 3: A typical drainage line in the study area



Figure 4: A typical, mosaic of grassland, crops and mining activity in the study area

## APPENDIX A: MICROHABITATS



Figure 5: The Tutuka-Kendal 400kV lines running through a wetland. The existing lines in the study area are having an impact on birds through collision mortality.



Figure 6: One of 12 Lesser Flamingos found under the Tutuka-Kendal 400kV line during the field inspections.