

The Matimba waste rock dump with the Power Station located to the east of the dump




The existing Matimba Rock dump, the red line shows the boundaries of the rock dump, looking north east



The view of the waste rock dump in relation to the Matimba Power Station, looking east



The Matimba Rock dump viewed from the west, note the height of the bund surrounding the site



Examples of rock waste and concrete waste dumped on the site, to the north east



Common waste rock observed on the dump



Some examples of general waste that was observed inside the waste dump



Additional examples of waste dumped inside dump



Common example of vegetation and grass species located inside the waste dump



General vegetation surrounding the waste dump